

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:				
OGM	Pete Hess Environmental Scientist III			
Company	Scott Dimick Superintendent			

Inspection Report

Permit Number:	C0070033		
Inspection Type:	PARTIAL		
Inspection Date:	Monday, February 07, 2005		
Start Date/Time:	2/7/2005 11:45:00 AM		
End Date/Time:	2/7/2005 12:50:00 PM		
Last Inspection:	Tuesday, January 11, 2005		

Inspector: Pete Hess, Environmental Scientist III
Weather: Partly cloudy; 40's F. Front moving in.

InspectionID Report Number: 527

Accepted by: whedberg 2/27/2005

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: PO BOX 902, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages	Mineral Ownership	Types of Operations

100.00	Total Permitted	✓ Federal	Underground
63.70	Total Disturbed	☐ State	Surface
	Phase I	☐ County	✓ Loadout
	Phase II	☐ Fee	✓ Processing
	Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee continues to meet the requirement in the Special Permit Condition included in Attachment "A" of the current State permit by submitting all surface water monitoring information to the Division EDI on a quarterly basis.

Inspector's Signature

Date

Monday, February 07, 2005

Pete Hess, Environmental Scientist III Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Monday, February 07, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.8	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.	o Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Monday, February 07, 2005 Page 3 of 3

3. Topsoil

The permittee needs to redefine the retainment ditch about the base of the topsoil pile which is located next to sediment pond "E". The topsoil storage sign was in place. There were no coal fines visible on the surface of this pile. It must be noted that the soil moisture conditions at the site are very soft, making any needed ditch maintenance impossible. The permittee must wait for drier conditions in order to address this problem.

4.a Hydrologic Balance: Diversions

All of the diversions which were inspected appeared to be capable of functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Ponds A, C, D, E, and F were inspected. Pond C contained the most water. Pond F was frozen; there were no compliance issues noted at any of the ponds.

16.a Roads: Construction, Maintenance, Surfacing

All roads appeared to be in good condition with the exception of the road passing by pond "B". This is an unsurfaced road, and the surface appeared to be quite soft. Pond "B" was not inspected this day due to the soft road condition. There were two piles of snow removal material (snow, coal, and road base material) observed at the SW corner of pond "A" and on the south end of the loadout pad. Mr. Dimick was asked to remove these after the snow has melted out and dispose of the remaining material on the coal refuse pile. The permittee's representative agreed to this request.